


Property Address

Sample Street, Sample Town, XX1 1XX



PinPoint certification

PinPoint Certifies the accuracy of the data in these reports. This Certification is supported by a £1M per claim Indemnity, provided by Aviva.

What is within scope of the Certification can be found at
<https://www.pinpointinformation.co.uk/landmark-coal-certificate-v1>

Underground mining

↗	Past underground mining	Page 2	Not identified
↑	Present underground mining	Page 2	Not identified
↖	Future underground mining	Page 2	Not identified

Opencast mining

⚙	Past opencast mining	Page 3	Not identified
⚙	Present opencast mining	Page 3	Not identified
⚙	Future opencast mining	Page 3	Not identified

Mining (other)

🏠	Mine entries	Page 4	Not identified
🏠	Mining geology	Page 4	Not identified
💧	Mine gas	Page 4	Not identified
🏠	Subsidence claims	Page 4	Not identified
⚠	Surface hazards	Page 4	Not identified
💎	Minerals other than coal	Page 4	Not identified

This Report identifies potential risk(s). Details of the risk(s) and suggested further steps are reported overleaf. Please Note: The risk assessments are based on licensed Coal Authority and PinPoint data as interpreted by PinPoint Coal Ltd

Phil Huddleston MRICS, Chartered Minerals Surveyor
Director of PinPoint Coal Ltd

Underground mining

Past underground mining

Not identified ✓

The property is not in an area where there are any maps to show that workings of coal have taken place within influencing distance of the property.

Present underground mining

Not identified ✓

The property is not in the likely zone of influence of any present underground coal workings.

Future underground mining

Not identified ✓

The Coal Authority has not granted a licence to extract coal using underground methods in the area of this property.

Opencast mining

Past opencast mining

Not identified ✓

The property is not inside the boundary of an opencast site from which coal has been removed by opencast methods.

Present opencast mining

Not identified ✓

The property is not within 200 metres of an opencast site from which coal is being removed by opencast methods.

Future opencast mining

Not identified ✓

The property does not fall within 800 metres of an opencast site for which the Coal Authority is determining whether to grant a licence to remove coal by opencast methods.

Mining (other)

Mine entries

Not identified ✓

Mine Entry Interpretation Report

This section of expands on the standard mine entry reporting by providing additional information about the mine entries and a risk assessment.

Coal Authority records indicate that there are no known or recorded mine entries present within the boundary of the property, or within 20M surrounding it.

Mining geology

Not identified ✓

No geological fissures, breaklines and/or other lines of weakness are present in the area that may have been affected or created by coal mining.

Mine gas

Not identified ✓

There is no record of any action being required by the Coal Authority as a result of a mine gas emission within the boundary of the property.

Subsidence claims

Not identified ✓

The Coal Authority has not received a damage notice or claim for the property since 1 January 1994. There is no current Stop Notice delaying the start of remedial works or repairs to the property.

Surface hazards

Not identified ✓

There is no record of any action being required by the Coal Authority as a result of a surface hazard within the boundary of the property.

Minerals other than coal

Not identified ✓

British Geological Survey records reveal no known mining in this area

Appendices

Understanding the data	7
Useful information	8
Important consumer protection information	8
Terms & condition and copyright statement	9



Understanding the data

NOTES

- This official CON29M Residential Coal Mining Report is a site-specific interpretation of coal mining activity. These enquiries are The Law Society CON29M Coal Mining search enquiries and are used with permission of The Law Society. The Law Society CON29M Coal Mining search enquiries are protected by copyright owned by The Law Society of 113 Chancery Lane, London WC2A 1PL.
- These enquiries are produced in conjunction with the Law Society's Terms and Conditions 2018, User Guide 2018, and the Guidance Notes 2018, under which all replies to these enquiries are made. These terms apply regardless of the method used to order and receive reports. The Terms and Conditions and User Guide have been approved by the Law Society following consultation with key stakeholders and apply to all searches made including those using the CON 29M enquiry form.

Coal

Underground coal mining

The report has identified what, if any, treatment is known to have been provided to the mine entries disclosed. Where treatment is unknown this does not mean none has taken place but simply that the Coal Authority does not have any record of it. This is because before the formation of the National Coal Board there was no centralised recording facility and the treatment was reliant upon private operators and landowners.

If after reading this you are concerned about any of the issues raised here and wish to obtain further advice other than our Consultants Report, you will need to have a further detailed investigation undertaken and a report prepared by a suitably qualified professional; then follow any guidance given in that report.

Pinpoint Zone of Influence

Landmark reports use a bespoke methodology to determine the zone of influence that is unique to them and highly accurate. The average depths of underground workings within the Zone Of Influence are reported by indicating the percentage depths for shallow workings (those less than 30M or 50M where the seam is unusually thick), moderate (depth ranges from 30M to 500M) and considerable (workings deeper than 500M). A count of the number of seams worked and the last date of mining from these is also reported.

Mine entries

Shafts and adits are the means by which coal is accessed from the surface. Shafts are vertical excavations sunk from the surface to the coal seams worked. Adits are tunnels that start at the surface and extend into the seams worked. The approximate location of any mine entries within 20M of the property boundary are referred to and shown on the plan.

Summary

The report has identified what, if any, treatment is known to have been provided to the mine entries disclosed. Where treatment is unknown this does not mean none has taken place but simply that the Coal

Authority does not have any record of it. This is because before the formation of the National Coal Board there was no centralised recording facility and the treatment was reliant upon private operators and landowners.

If after reading this you are concerned about any of the issues raised here and wish to obtain further advice other than our Consultants Report, you will need to have a further detailed investigation undertaken and a report prepared by a suitably qualified professional; then follow any guidance given in that report.

Subsidence claims

The individual details of each claim are listed above. Further actions are recommended based on the particular status of a claim.

- **Claim Withdrawn**- no action generally but if damage was identified in the property there may be causes other than mining subsidence. Advise making further enquiry with the vendor.
- **Claim Ongoing**- make further enquiries of the Seller, their Solicitors or the Coal Authority.
- **Claim Settled**- where further detail is required, seeking a Subsidence Claims History report from the Coal Authority might provide useful information as to, for example, why the compensation was so high/low.

The existence of nearby claims does not necessarily mean that damage has been caused to other properties in the locality or will do so in the future. While there may not have been damage there most certainly will have been subsidence. The only method by which you can be sure no damage has been caused is to have an inspection undertaken.

Useful information

Statutory support

Under the Coal Mining Subsidence Act 1991, property owners have statutory protection. This provides that (save for coal worked through the Grant of Gale in the Forest of Dean, or any part of the Hundreds of St Briavels) damage caused by lawful disused coal mine workings or coal mine entries, shall be made good by the Coal Authority/Licensee to the reasonable satisfaction of the property owner. These sort of claims, need not usually involve either the home insurance company or mortgage lender. Further information can be obtained at www.gov.uk/government/publications/coal-mining-subsidence-damage-notice-form.

The Coal Authority provides an emergency call out facility in coalfield areas to assess the public safety implications of mining feature. These include disused coal mine entries, shafts and coal related surface hazards. More information can be found at www.groundstability.com. The Public Safety and Subsidence Department can be contacted through the Coal Authority's emergency telephone number is 01623 646333.

Report limitations

This Landmark Mining report has been carried out via the GIS of PinPoint Information Ltd, using a combination of TCA licensed data, British Geological Survey licensed data © NERC (2016), and PinPoint Information Ltd's digital collection of abandoned mine plans, maps, records and archives. Only in the case of a PinPoint Ground Stability report/module, does the report consider natural ground stability hazards, such as subsidence, landslip or coastal erosion. Only in the case of a PinPoint Minerals report/module and the combined coal and minerals report/module is ground stability through the extraction of minerals fully considered.

Some of the responses contained in this report are based on data and information provided by the United Kingdom Research and Innovation (UKRI) or its component body the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither UKRI nor BGS gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law.

This report is concerned solely with the Site searched and should not be used in connection with nearby properties, as only known features that could potentially have a direct influence upon the Site searched are considered relevant, with other (non-relevant) features present in the general area being omitted for ease of reference.

Landmark reports assess the risk posed in relation only to objectively identifiable criteria. For example, in the case of a Landmark Regulated Report, the assessment relates only to the type of hazards typically outlined in a Coal mining report answering Con29M questions as agreed from time to time by the Coal Authority and the Law Society of England & Wales. In this regard, from June of 2018, content relating to the activities of the Cheshire Brine Compensation Board ceased to be a requirement of a Con29M. As such, it is beyond the scope of this report to provide any information relating to the activities of the Cheshire brine Compensation Board.

Landmark recommends that should a location be identified as being within the Cheshire Brine RESIDENTIAL Compensation Area a Cheshire Salt report should be secured from your search provider.

It is beyond the scope of this Report to assess the potential loss amenity or aesthetic impact of certain hazards. For example, current or proposed open cast workings, despite their existence possibly affecting the Site's resale value.

This report is confidential to the client, the client's legal advisor and the client's Mortgage lender, as defined in the Landmark terms & conditions, and as such may be used by them for conveyancing or related purposes. RESIDENTIAL

If you wish to discuss the relevance of any of the risk information contained in this report you should seek the advice of a qualified mining engineer or surveyor. If you or your adviser wish to examine the source plans from which the information has been taken these are normally available at the Coal Authority's offices: 200 Lichfield Lane, Berry Hill, Mansfield, Nottinghamshire NG1 4RG. They are viewable, by prior appointment, telephone 01623 637235 or in the case of minerals via the on-line facility afforded by British Geological Survey.

Should you or your adviser wish to carry out any physical investigations that may enter, disturb or interfere with any disused mine entry or shallow workings, the prior permission of the owner must be sought. For coal mine entries and workings the owner will normally be the Coal Authority. With other Minerals, do not assume that the owner is the surface land owner, as ownership might previously have been severed.

Important consumer protection information



This search has been produced by:

Landmark Information Group Limited

Imperium
Imperial Way
Berkshire
RG2 0TD

✉ helpdesk@landmark.co.uk

☎ 0330 036 6619

Conveyancing Information Executive (CIE) standards

Landmark adheres to the Conveyancing Information Executive (CIE) standards

- Conveyancing Information Executive Members shall act in a professional and honest manner at all times in line with the Conveyancing Information Executive Standards and carry out the delivery of the Search with integrity and due care and skill.
- Compliance with the Conveyancing Information Executive Standards will be a condition within the Conveyancing Information Executive Member's Terms and Conditions.
- Conveyancing Information Executive Members will promote the benefits of and deliver the Search to the agreed standards and in the best interests of the customer and associated parties.
- The standards can be seen here: <http://www.conveyinfoexec.com>

Complaints

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/ or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Standards. Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPO.

TPOs

The Property Ombudsman scheme
Milford House
43-55 Milford Street
Salisbury
Wiltshire SP1 2BP

🌐 www.tpos.co.uk

✉ admin@tpos.co.uk

☎ 01722 333306

Complaints procedure

If you want to make a complaint to Landmark, we will:

- Acknowledge it within 5 working days of receipt.
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt.
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time.
- Provide a final response, in writing, at the latest within 40 working days of receipt.
- Liaise, at your request, with anyone acting formally on your behalf.

Complaints should be sent to:

Customer Services Manager

Landmark Information
Imperium
Imperial Way
Reading
RG2 0TD

✉ helpdesk@landmark.co.uk

☎ 0330 036 6619

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman. We will co-operate fully with the Ombudsman during an investigation and comply with his final decision

Terms and conditions and copyright statement

Landmark Standard Terms and Conditions

Landmark Standard Terms and Conditions can be found here: <https://www.landmark.co.uk/wp-content/uploads/2022/07/landmark-terms-and-conditions-299431-8.0-content.pdf>. Should you experience difficulties, please call our Customer Service Team on 0330 036 6619.

All rights reserved. You must not reproduce, store or transmit any part of this document unless you have our written permission. ©2024 Landmark Information Group Ltd.

Pinpoint certification (for coal mining)

PinPoint Certifies the accuracy of the data in these reports. This Certification is supported by a £1M per claim Indemnity, provided by Aviva. What is within scope of the Certification can be found at:

www.pinpointinformation.co.uk/landmark-coal-certificate-v1

Coal data licensing

This report contains Data provided by the Coal Authority. Any and all analysis and interpretation of Coal Authority Data in this report is made by PinPoint Coal Ltd, and is in no way supported, endorsed or authorised by the Coal Authority. The use of the data is restricted to the terms and provisions contained in this report. Data reproduced in this report may be the copyright of the Coal Authority and permission should be sought from PinPoint Coal Ltd prior to any re-use